

Conford House Listed Grade II

House. C16, late C17 and early C19. Walls of ironstone (painted) with



ironstone, other stone and brick dressings: 1st floor band of ironstone with tile bands above and below, plinth: a hoodmould to a north door and a Tudor-arched doorway now filled: many earlier openings now filled: the west wall has massive exposed framing with brick infill, and

a brick wall to the outshot below. Tile roof, 1/2-hipped, catslide at rear, 3 small hipped dormers. A timber-framed house with later cladding on 3 elevations; south front of 2 storeys and attic, 3 windows. Sashes in

exposed frames to the front, casements elsewhere. French door. The north doorway has a C18 plain

frame with a 6-panelled door. Within

the west end outshot, the lower part of the west

This part of Conford was originally a detached portion of Oakhanger Manor.

Conford House is a beautiful example of Jacobean architecture. All the windows overlook farm fields, trees and water, the same fields still growing corn and flax



RIGHT
DRAWING OF TIMBER
FRAMING

